




August 16, 2017

1:2,400

 Tax Parcels





Figure 7 - Potential Monitoring Well Locations
 PCE Plume Evaluation - Unit Well 8
 SCS Project 2521516.00

 Potential Well Locations Along Likely Contaminant Flow Paths That Are Not Obstructed by Terrace Trees or Overhead Utilities are Shown in **Blue**